MSFC Safety Bulletin


Crosby Swivel Hoist Rings Recalled

What Happened?

- The Crosby Group, Inc., a manufacturer of rigging equipment, has recalled HR-125 and HR-125M Swivel Hoist Rings from a specific production lot.
- Use of the specified rings may result in property damage, severe injury, or death.

What Can Be Done?

- Locate all items in stock and in service, sized as shown in table at right. Find and remove from service those marked with Product Identification Code 'Y5C' on the bail, or 'Z7C' on the bolt.
- Contact your Crosby distributor to arrange for replacement.
- Contact Terry Johnson at 1-800-772-1500 or EG&G/Donald Smith at 544-4007 for questions or more information.
- Notify all other possible users of Crosby swivel hoist rings about this recall.



HR-125	HR-125M
1.50-inch, 24,000 lb rating	M 36, 11,000 kg rating
HR-125 P/N 1016986	HR-125M P/N 1016690
2.00-inch, 30,000 lb rating	M 42, 12,500 kg rating
HR-125 P/N 1016997	HR-125M P/N 1016701
	M 48, 13,500 kg rating HR-125M P/N 1016712